SENECA COUNTY GENERAL HEALTH DISTRICT

71 S. Washington Street, Suite 1102, Tiffin, Ohio 44883
419-447-3691 – 1-800-698-3691 – FAX: 419-448-5782
Fostoria Satellite Office: 419-435-4401 – FAX: 419-435-3024
Visit us on the web: www.senecahealthdept.org

Anne Goon, MS, RD, LD, Health Commissioner

November 18, 2021

Brian Ezyk
Sunny Farms Landfill LLC
12500 W Co Rd 18
Fostoria, OH 44830

Subject: Sunny Farms Landfill, Seneca County
Letter of Compliance

Dear Mr. Ezyk:

Thank you for having Brian Graves accompany me during the Seneca County General Health District's November 18, 2021, inspection of Sunny Farms Landfill in Seneca County Ohio. This was a comprehensive inspection. The goal of my inspection was to determine compliance with Ohio's laws as found in Chapter 3734 of the Ohio Revised Code (ORC) and Chapter 3745-27 of the Ohio Administrative Code (OAC), the terms and conditions of the facility's permit-to-install and the Seneca County Court Consent Order 19-CV-0224, issued July 26, 2019. The inspection included a review of company operations and written documentation associated with facility operations.

No violations were discovered during this inspection.

Please be advised that this letter of compliance is only associated with those areas of the operations that were inspected or documentation reviewed and does not constitute a waiver of potential violations not discovered.

Should you have any questions, please contact me at 419-447-3691 x6323 or anainiger@senecahealthdept.org

Sincerely,

Austin Nainiger
Seneca County General Health district

Enclosure: Inspection Checklist

ec: Tyler Madeker, Ohio EPA, DMWM-NWD
Brian Ezyk, Sunny Farms Landfill, LLC
Brad Bashore, Sunny Farms Landfill, LLC

SENECA COUNTY GENERAL HEALTH DISTRICT
Public Health
Prevent. Promote. Protect.

Municipal Solid Waste Landfill Inspection Checklist

Facility/Location Name:	**Sunny Farms Landfill LLC**		
☑ **Comprehensive Inspection**		**Date of Last Inspection:**	**11/12/2021**
☐ **Focused Inspection**	**Specify Item Number(s)**		
Address:	**12500 W. County Road 18 Fostoria, Ohio 44830**		
Date:	**11/18/2021**	**Time:**	**9:30 AM**
Weather:	**40° 26mph WSW**		
Inspection Representatives			
Facility:	**Brain Graves**	**Health District:**	**Austin Nainiger**
Ohio EPA:	**Not Present**		
Others Present:	**N/A**		

For each item below, mark "Y" if Yes, "N" if No, "DNI" if Did Not Inspect this item, "NA" if Not Applicable

Item	Y	N	DNI	NA	* indicates this item should be reviewed prior to the field inspection	Rule Reference
Administrative						
1*	☐	☐	☑	☐	Are license terms/conditions being followed?	3745-27-19(B)(1)
2*	☐	☐	☑	☐	Are Permit-to-Install (PTI) terms/conditions, listed on page 3, being followed?	3745-27-19(B)(2)
3*	☑	☐	☐	☐	Are the Seneca County Court Orders, listed on page 3, being followed?	3745-27-19(B)(2)
4*	☐	☐	☐	☑	Have all alterations listed on page 3 been added to the appropriate document?	3745-27-19(B)(2)
5	☐	☐	☑	☐	Is the daily log of operations form complete?	3745-27-19(E)(10)(a)
6	☑	☐	☐	☐	Is the daily log of operations form available for the previous three years?	3745-27-19(E)(10)(d)
7	☐	☐	☑	☐	Is the o/o inspecting for ponding, erosion, and leachate outbreaks daily on Form 3?	3745-27-19(E)(11)(a)
8	☐	☐	☑	☐	Is the o/o inspecting the sed ponds and surface water structures weekly on Form 4?	3745-27-19(E)(11)(b)
9	☑	☐	☐	☐	Is the odor complaint log available and up-to-date?	Court Order 16L
10	☑	☐	☐	☐	Is the video recording of railcar unloading being maintained for 90 days?	Court Order 16W
Access						
Item	**Y**	**N**	**DNI**	**NA**		**Rule Reference**
10	☐	☐	☑	☐	Is only naturally occurring vegetation being cleared for proper operation?	3745-27-19(E)(1)(a)
11	☑	☐	☐	☐	Are the roads being maintained to allow the passage of a loaded refuse vehicle?	3745-27-19(E)(2)(a)
12	☑	☐	☐	☐	Is mud, debris, and dirt being removed from Twp. Road 108 at least once per day?	Court Order 16Q
13	☑	☐	☐	☐	Are measures in place to limit access (ie; gate, padlock, berm, ditch)?	3745-27-19(E)(2)(b)
14	☑	☐	☐	☐	Are yard waste restriction signs posted at each public entrance?	3745-27-19(E)(2)(c)
15	☑	☐	☐	☐	Are farm/domestic animals excluded from the operating areas?	3745-27-19(E)(2)(d)
Equipment						
Item	**Y**	**N**	**DNI**	**NA**		**Rule Reference**
16	☑	☐	☐	☐	Is adequate equipment, material and services, marked on page 3, available to control fire?	3745-27-19(E)(3)(a)
17	☑	☐	☐	☐	Is equipment of adequate size and quantity, marked on page 3, available at all times?	3745-27-19(E)(3)(b)
Waste Acceptance						
Item	**Y**	**N**	**DNI**	**NA**		**Rule Reference**
18	☑	☐	☐	☐	Are preparations in place to receive waste during inclement weather?	3745-27-19(E)(6)
19	☑	☐	☐	☐	Is the unloading of waste material confined to the smallest practical area(s)?	3745-27-19(E)(7)(c)
20	☑	☐	☐	☐	Is all waste being deposited at the working face?	3745-27-19(E)(7)(e)
21	☑	☐	☐	☐	Is all waste being compacted?	3745-27-19(E)(7)(e)
22	☐	☐	☑	☐	Is waste being spread in layers of not more than two feet?	3745-27-19(E)(7)(e)
23	☐	☐	☑	☐	Are strategies in place to manage bulky materials enabling daily cover to be placed?	3745-27-19(E)(7)(f)(i)
24	☑	☐	☐	☐	Are strategies in place to manage dusty materials?	3745-27-19(E)(7)(f)(ii)
25	☐	☐	☑	☐	Are the disposal restrictions, listed on page 3, being followed?	3745-27-19(E)(8)
26	☐	☐	☑	☐	Are the working faces limited to 3.5 acres?	Court Order 16B
27	☐	☐	☑	☐	Are drilling operation materials being handled/documented appropriately?	ORC 3734.02(Q)
Operations						
Item	**Y**	**N**	**DNI**	**NA**		**Rule Reference**
28	☑	☐	☐	☐	Are noise, dust, and/or odors being controlled?	3745-27-19(B)(3)
29	☑	☐	☐	☐	Are adequate vector controls/control strategies available at the facility?	3745-27-19(B)(4)
30	☑	☐	☐	☐	Are the access roads being maintained to minimize dust and erosion?	3745-27-19(E)(2)(a)
31	☑	☐	☐	☐	Is a water truck being used or available to minimize dust generation on access roads?	3745-27-19(E)(2)(a)

Facility Name:	Sunny Farms Landfill LLC	Date:	11/18/2021	Page 2

Operations continued						
Item	Y	N	DNI	NA	* indicates this item should be reviewed prior to the field inspection	Rule Reference
32	☑	☐	☐	☐	Is an operator, as defined in 3745-27-01, familiar with operations/documents?	3745-27-19(E)(5)
33*	☑	☐	☐	☐	Is the correct phase, listed on page 3, being filled?	3745-27-19(E)(7)(b)
34	☑	☐	☐	☐	Is the working face supervised by a person knowledgeable of its operations?	3745-27-19(E)(7)(c)
Litter						
Item	Y	N	DNI	NA		Rule Reference
35	☑	☐	☐	☐	Are measures in place to collect, contain and dispose of litter?	3745-27-19(E)(9)
36	☑	☐	☐	☐	Are litter pickers, listed on page 3, on-site?	3745-27-19(E)(9)
37	☑	☐	☐	☐	Is litter fencing in place?	3745-27-19(E)(9)
Cover						
Item	Y	N	DNI	NA		Rule Reference
38	☑	☐	☐	☐	Is only soil being used as daily cover?	Court Order C
39	☐	☐	☑	☐	Is a minimum of six inches of soil daily cover applied and maintained?	3745-27-19(F)(1)
40	☐	☐	☐	☑	Is one of the approved alternative daily cover (ADC) listed on page 3 being used?	3745-27-19(F)(3)
41	☐	☐	☐	☑	Is the ADC being used in accordance with the Director's approval letter?	3745-27-19(F)(3)
42	☑	☐	☐	☐	Is intermediate cover being protected from erosion (ie, silt fencing, vegetation)?	3745-27-19(G)(4)
43	☑	☐	☐	☐	If transitional cover is in place, is it densely vegetated? (3745-27-08(D)(19)(b))	3745-27-19(H)(2)(a)
44	☑	☐	☐	☐	If final cap is in place, is it densely vegetated? (3745-27-08(D)(26)(e)(ii))	3745-27-19(H)(2)(b)
45	☐	☐	☑	☐	Is a 24-inch thick layer of well-compacted soil being used for intermediate cover?	Court Order 16D
46	☐	☐	☑	☐	Is a 36-inch thick layer of well-compacted soil being maintained on Area 2?	3745-27-19(G)(4)
Surface Water Management						
Item	Y	N	DNI	NA		Rule Reference
47	☑	☐	☐	☐	Are stormwater features constructed/maintained for stormwater conveyance?	3745-27-19(J)(1)
48	☑	☐	☐	☐	Are strategies in place to correct the conditions causing ponding or erosion?	3745-27-19(J)(3)
Leachate Management						
Item	Y	N	DNI	NA		Rule Reference
49	☑	☐	☐	☐	Are leachate sump/tank readings, listed on page 3, within the compliance limits?	3745-27-19(E)(1)(c)
50	☐	☐	☐	☑	Are leachate outbreaks documented on log of operations?	3745-27-19(E)(11)(a)
51	☐	☐	☑	☐	Are leachate outbreaks present?	3745-27-19(K)(1)(a)(c)
52	☐	☐	☐	☑	If leachate outbreaks are present, are the outbreaks being properly managed?	3745-27-19(K)(1)(a)(c)
53	☑	☐	☐	☐	Is at least one back-up lift station pump available at the facility?	3745-27-19(K)(2)
54	☐	☐	☑	☐	Is the hydrogen peroxide leachate treatment system operating?	3745-27-19(K)(5)
55	☑	☐	☐	☐	Is leachate being treated/disposed on-site/off-site appropriately?	3745-27-19(K)(5)
Ancillary Structures / Engineered Components						
Item	Y	N	DNI	NA		Rule Reference
56	☑	☐	☐	☐	Are observed engineered components functioning appropriately?	3745-27-19(E)(1)(c)
57	☐	☐	☑	☐	Are observed ground water wells (3745-27-10) being maintained?	3745-27-19(E)(1)(c)
58	☐	☐	☑	☐	Are observed explosive gas monitoring wells (3745-27-12) being maintained?	3745-27-19(E)(1)(c)
59	☐	☐	☑	☐	Are observed gas extraction wells / gas vents being maintained?	3745-27-19(E)(1)(c)
60	☑	☐	☐	☐	Is the hydrogen sulfide control system operating?	3745-27-19(E)(1)(c)
61	☑	☐	☐	☐	Are the observed permanent Jerome meters/locations being maintained?	Court Order 16A
62	☐	☑	☐	☐	Is the primary flare operating?	3745-27-19(E)(1)(c)
63	☑	☐	☐	☐	Is the back-up generator being maintained to ensure continous operation of the flares?	Court Order 16N
Railcars / Rail Unloading Building						
Item	Y	N	DNI	NA		Rule Reference
64	☐	☐	☑	☐	Is the rail unloading building's leachate tank high level alarm functioning?	3745-27-19(E)(1)(c)
65	☑	☐	☐	☐	Is the rail unloading building's floor grates clear to allow the collection of leachate?	3745-27-19(E)(1)(c)
66	☑	☐	☐	☐	Are measures in place to collect, contain and dispose of litter around the rail building?	3745-27-19(E)(9)
67	☑	☐	☐	☐	Is litter fencing present between the rail unloading building and sedimentation pond?	Court Order 16S
Scales						
Item	Y	N	DNI	NA		Rule Reference
68	☑	☐	☐	☐	Is the front entrance scale operational? List certification on Page 4.	3745-27-19(I)
69	☑	☐	☐	☐	Is the railcar scale operational? List certification on Page 4.	Court Order 16U

Additional Documentation

Item	Y	N			
70	☑	☐	Was photo documentation gathered?	☐	Photos attached
71	☐	☑	Were hydrogen sulfide levels documented using a Jerome meter?	☐	Results attached

Item	Information								
1	License terms/conditions:	☐	2021 license conditions are being followed						
2	Permit-to-Install (PTI) terms and conditions applicable to the inspection:	Condition #25	☐	AMDWR is 7500 tons/day					
		Condition #26	☐	AMDWR report due by the 15th of following month					
		Condition #26	☐	Leachate report due by the 15th of following month					
3	Seneca County Court Consent Order		Applicable orders from the July 26, 2019, Seneca County Court Consent Order (19-CV-0224) are incorporated into the checklist.						
4	List all alterations issued since the last inspection:	Alteration #		Type:					
		Alteration #		Type:					
		Alteration #		Type:					
	☑ No alterations issued	Alteration #		Type:					
		Alteration #		Type:					
16	Mark boxes to indicate what types of fire control equipment is available on-site:		☑	Bulldozer		☑	Soil Stockpile		
			☑	Compactor		☑	911 Service Available		
			☑	Fire Extinguisher(s)		☑	Water Truck		
17	Equipment available - mark boxes/quantity		☑	Bulldozers	#4	☑	Compactor	#1	
	Contingency plan available if no back-up		☐	Scrapers	#	☑	Trucks	#10	
	Contingency plan reviewed		☑	Other	1 front end loader, 1 broom, 4 excavators, 1 locomotive, 1 trackm mobile				
25	Disposal restrictions, 3745-27-19(E)(8), include NESHAP regulated asbestos unless authorized, liquids unless authorized, hazardous waste, PCBs, infectious waste, source separated yard waste, whole or shredded scrap tires, low-level radioactive waste, and semi-solid materials with free liquids								
33	Current permitted phase designation		12						
36	Litter Pickers	Affiliation:	Surge/SFL				Number:	6	
40	Alternative daily covers (ADC) approved for use and the approval date. Mark box(es) of the ADC being utilized. **In accordance with the consent order, only soil is currently approved for daily cover.**		☐	Topcoat spray-on-slurry	7/10/2001				
			☐	VWPFR-12 Tarp	7/10/2001				
			☐	WP-1440SB Tarp	7/10/2001				
			☐	WP1440FR Tarp	7/10/2001				
			☐	WP2200SB Tarp	7/10/2001				
			☐	WP2600 Tarp	7/10/2001				
			☐	Integra 12FR Tarp	7/10/2001				
			☐	Proguard 11B Plus spray-on-slurry	10/3/2006				

						SCADA/IN FIELD		
49	Leachate sump readings - compliance level vs actual reading	Closed North PS #1, 2A	Compliance	18 inches	Reading	16/ 15.83	Auto On	☑
		Closed North PS #2, 2C	Compliance	18 inches	Reading	--	Auto On	☐
		Closed North PS #3, 3A	Compliance	18 inches	Reading	15/14.48	Auto On	☑
		Closed North PS #4, 3C	Compliance	18 inches	Reading	14/14.05	Auto On	☑
		Closed North PS #5, 4A	Compliance	18 inches	Reading	15/14.65	Auto On	☑
		Closed North PS #6, 4B (4C on SCADA)	Compliance	18 inches	Reading	15/14.83	Auto On	☑
		Closed North PS #7, 5A	Compliance	18 inches	Reading	--	Auto On	☐
		Closed North PS #8, 5B	Compliance	18 inches	Reading	14/13.69	Auto On	☑
		Closed North PS #9, 6A	Compliance	18 inches	Reading	17/16.7	Auto On	☑
		Closed North PS #10, 6B	Compliance	18 inches	Reading	16/16.21	Auto On	☑
		Closed North PS #11, 7	Compliance	18 inches	Reading	16/16.46	Auto On	☑

Facility Name:		Sunny Farms Landfill LLC				Date:	11/18/2021		Page 4
49		Leachate sump readings - compliance level vs actual reading	South Sump #8A	Compliance	36 inches	Reading	18/16.98	Auto On	☑
			South Sump #8B	Compliance	36 inches	Reading	17/17.38	Auto On	☑
			South Sump #9B	Compliance	36 inches	Reading	18/17.6	Auto On	☑
			South Sump #10A	Compliance	36 inches	Reading	17/15.46	Auto On	☑
			South Sump #13	Compliance	36 inches	Reading	19.88	Auto On	☑
			South Sump #12 temporary	Compliance	36 inches	Reading		Auto On	☐
49		Leachate storage tanks inspection. Tank readings, capacity and high level shutoff are recorded in feet	Tank #1 (East)	Secondary Containment	☐		Visual Insp (leaks, rust)		☐
			Tank Reading	0	Height	16.12	High Level Shutoff		13
			Tank #2 (West)	Secondary Containment	☐		Visual Insp (leaks, rust)		☐
			Tank Reading	2.63	Height	24.18	High Level Shutoff		20
			Tank #3 (South)	Secondary Containment	☐		Visual Insp (leaks, rust)		☐
			Tank Reading	13.23	Height	28.06	High Level Shutoff		26.5
60		Hydrogen sulfide control system	# of control boxes on-site		DNI		# of control boxes in use		DNI
62		Flare operations	Flare 1	Temperature:	DNI	Flow:	DNI	Pressure:	DNI
			Flare 3	Temperature:	DNI	Flow:	DNI	Pressure:	DNI
68		Front entrance scale	Last Inspection:	7/17/2021	Agency:	Brechbuhler Scales			
69		Rail scale	Last Inspection:	8/15/2021	Agency:	Seneca Weights and Measure and Rail Scale			

#	Item/Information Section
28	Misting system in the unloading building was down due to electical system, waste was still being sprayed and dust was minimal
67	The litter fence behind the excavator doors of the unloading building looks like it was backed into by an excavator and needs to be repaired
42	East slope above the haul road has large erosion runs from recent heavy rains, a verbal understanding/agreement was made to remedy the issue this time next month
62	When I arrived on site the flare was down for maintence, however due to high winds the flare was returned to operation and maintence will resume when wind speeds decrease.
63	The generator in the flare area has an automatic startup every Monday and is maintained by Generac quarterly.
66	Litter needs picked around the rail to the north of the unloading building.
49	Cell 5A leachate sump was down for electrical maintenance.

#	General Comments Section

Select Waste

Item	Y	N	DNI	NA		Rule Reference
72	☐	☑	☐	☐	Is the select waste layer (SWL) being placed? If Yes, complete items #73-82	3745-27-19(D)
73	☐	☐	☐	☑	Is the SWL being spread and not compacted?	3745-27-19(D)(1)(a)
74	☐	☐	☐	☑	Does the SWL contain items under two feet in length?	3745-27-19(D)(1)(b)
75	☐	☐	☐	☑	Does the SWL allow the flow of liquids to the leachate collection system?	3745-27-19(D)(1)(c)
76	☐	☐	☐	☑	Is the SWL free of fines and small particles?	3745-27-19(D)(1)(d)
77	☐	☐	☐	☑	Is the SWL being placed as a single lift of a minimum of five feet?	3745-27-19(D)(1)(e)
78	☐	☐	☐	☑	Was the SWL documentation submitted to the operating record?	3745-27-19(D)(2)
79	☐	☐	☐	☑	Was the date of the SWL documented?	3745-27-19(D)(2)(a)
80	☐	☐	☐	☑	Was the location of the cell/phase of the SWL documented?	3745-27-19(D)(2)(b)
81	☐	☐	☐	☑	Was the thickness of the SWL documented?	3745-27-19(D)(2)(c)
82	☐	☐	☐	☑	Was the source and composition of the SWL documented?	3745-27-19(D)(2)(d)

Austin Nainiger	Austin Nainiger	11/18/2021
Print Name of Inspector Completing Inspection Form	**Signature**	**Date**

Last Revised: January 29, 2021