# SENECA COUNTY GENERAL HEALTH DISTRICT

**71 S. Washington Street, Suite 1102, Tiffin, Ohio 44883**
**419-447-3691 – 1-800-698-3691 – FAX: 419-448-5782**
**Fostoria Satellite Office: 419-435-4401 – FAX: 419-435-3024**
**Visit us on the web: www.senecahealthdept.org**

**Anne Goon, MS, RD, LD, Health Commissioner**


December 8, 2021

Brian Ezyk
Sunny Farms Landfill LLC
12500 W Co Rd 18
Fostoria, OH 44830

Subject: Sunny Farms Landfill, Seneca County
Letter of Compliance

Dear Mr. Ezyk:

Thank you for having Jeff Youngquist accompany me during the Seneca County General Health District's December 7, 2021, inspection of Sunny Farms Landfill in Seneca County Ohio. This was a comprehensive inspection. The goal of my inspection was to determine compliance with Ohio's laws as found in Chapter 3734 of the Ohio Revised Code (ORC) and Chapter 3745-27 of the Ohio Administrative Code (OAC), the terms and conditions of the facility's permit-to-install and the Seneca County Court Consent Order 19-CV-0224, issued July 26, 2019. The inspection included a review of company operations and written documentation associated with facility operations.

**No violations were discovered during this inspection.**

Please be advised that this letter of compliance is only associated with those areas of the operations that were inspected or documentation reviewed and does not constitute a waiver of potential violations not discovered.

Should you have any questions, please contact me at 419-447-3691 x6323 or anainiger@senecahealthdept.org

Sincerely,

Austin Nainiger
Seneca County General Health district

Enclosure: Inspection Checklist

ec: Tyler Madeker, Ohio EPA, DMWM-NWD
Brian Ezyk, Sunny Farms Landfill, LLC
Brad Bashore, Sunny Farms Landfill, LLC

SENECA COUNTY GENERAL HEALTH DISTRICT
Public Health
Prevent. Promote. Protect.

# Municipal Solid Waste Landfill Inspection Checklist

| | | | |
|---|---|---|---|
| **Facility/Location Name:** | **Sunny Farms Landfill LLC** | | |
| ☑ **Comprehensive Inspection** | | **Date of Last Inspection:** | **11/18/2021** |
| ☐ **Focused Inspection** | **Specify Item Number(s)** | | |
| **Address:** | **12500 W. County Road 18 Fostoria, Ohio 44830** | | |
| **Date:** | **12/7/2021** | **Time:** | **10:00 AM** |
| **Weather:** | **21° 8mph W 30.31** | | |

**Inspection Representatives**

| | | | |
|---|---|---|---|
| **Facility:** | **Jeff Youngquist** | **Health District:** | **Austin Nainiger** |
| **Ohio EPA:** | **Not Present** | | |
| **Others Present:** | **N/A** | | |

**For each item below, mark "Y" if Yes, "N" if No, "DNI" if Did Not Inspect this item, "NA" if Not Applicable**

**Administrative**

| Item | Y | N | DNI | NA | * indicates this item should be reviewed prior to the field inspection | Rule Reference |
|---|---|---|---|---|---|---|
| 1* | ☐ | ☐ | ☑ | ☐ | Are license terms/conditions being followed? | 3745-27-19(B)(1) |
| 2* | ☐ | ☐ | ☑ | ☐ | Are Permit-to-Install (PTI) terms/conditions, listed on page 3, being followed? | 3745-27-19(B)(2) |
| 3* | ☑ | ☐ | ☐ | ☐ | Are the Seneca County Court Orders, listed on page 3, being followed? | 3745-27-19(B)(2) |
| 4* | ☐ | ☐ | ☐ | ☑ | Have all alterations listed on page 3 been added to the appropriate document? | 3745-27-19(B)(2) |
| 5 | ☐ | ☐ | ☑ | ☐ | Is the daily log of operations form complete? | 3745-27-19(E)(10)(a) |
| 6 | ☑ | ☐ | ☐ | ☐ | Is the daily log of operations form available for the previous three years? | 3745-27-19(E)(10)(d) |
| 7 | ☑ | ☐ | ☐ | ☐ | Is the o/o inspecting for ponding, erosion, and leachate outbreaks daily on Form 3? | 3745-27-19(E)(11)(a) |
| 8 | ☑ | ☐ | ☐ | ☐ | Is the o/o inspecting the sed ponds and surface water structures weekly on Form 4? | 3745-27-19(E)(11)(b) |
| 9 | ☑ | ☐ | ☐ | ☐ | Is the odor complaint log available and up-to-date? | Court Order 16L |
| 10 | ☑ | ☐ | ☐ | ☐ | Is the video recording of railcar unloading being maintained for 90 days? | Court Order 16W |

**Access**

| Item | Y | N | DNI | NA | | Rule Reference |
|---|---|---|---|---|---|---|
| 10 | ☑ | ☐ | ☐ | ☐ | Is only naturally occurring vegetation being cleared for proper operation? | 3745-27-19(E)(1)(a) |
| 11 | ☑ | ☐ | ☐ | ☐ | Are the roads being maintained to allow the passage of a loaded refuse vehicle? | 3745-27-19(E)(2)(a) |
| 12 | ☐ | ☐ | ☑ | ☐ | Is mud, debris, and dirt being removed from Twp. Road 108 at least once per day? | Court Order 16Q |
| 13 | ☑ | ☐ | ☐ | ☐ | Are measures in place to limit access (ie; gate, padlock, berm, ditch)? | 3745-27-19(E)(2)(b) |
| 14 | ☑ | ☐ | ☐ | ☐ | Are yard waste restriction signs posted at each public entrance? | 3745-27-19(E)(2)(c) |
| 15 | ☑ | ☐ | ☐ | ☐ | Are farm/domestic animals excluded from the operating areas? | 3745-27-19(E)(2)(d) |

**Equipment**

| Item | Y | N | DNI | NA | | Rule Reference |
|---|---|---|---|---|---|---|
| 16 | ☑ | ☐ | ☐ | ☐ | Is adequate equipment, material and services, marked on page 3, available to control fire? | 3745-27-19(E)(3)(a) |
| 17 | ☑ | ☐ | ☐ | ☐ | Is equipment of adequate size and quantity, marked on page 3, available at all times? | 3745-27-19(E)(3)(b) |

**Waste Acceptance**

| Item | Y | N | DNI | NA | | Rule Reference |
|---|---|---|---|---|---|---|
| 18 | ☑ | ☐ | ☐ | ☐ | Are preparations in place to receive waste during inclement weather? | 3745-27-19(E)(6) |
| 19 | ☑ | ☐ | ☐ | ☐ | Is the unloading of waste material confined to the smallest practical area(s)? | 3745-27-19(E)(7)(c) |
| 20 | ☑ | ☐ | ☐ | ☐ | Is all waste being deposited at the working face? | 3745-27-19(E)(7)(e) |
| 21 | ☑ | ☐ | ☐ | ☐ | Is all waste being compacted? | 3745-27-19(E)(7)(e) |
| 22 | ☐ | ☐ | ☑ | ☐ | Is waste being spread in layers of not more than two feet? | 3745-27-19(E)(7)(e) |
| 23 | ☐ | ☐ | ☑ | ☐ | Are strategies in place to manage bulky materials enabling daily cover to be placed? | 3745-27-19(E)(7)(f)(i) |
| 24 | ☑ | ☐ | ☐ | ☐ | Are strategies in place to manage dusty materials? | 3745-27-19(E)(7)(f)(ii) |
| 25 | ☑ | ☐ | ☐ | ☐ | Are the disposal restrictions, listed on page 3, being followed? | 3745-27-19(E)(8) |
| 26 | ☑ | ☐ | ☐ | ☐ | Are the working faces limited to 3.5 acres? | Court Order 16B |
| 27 | ☐ | ☐ | ☐ | ☑ | Are drilling operation materials being handled/documented appropriately? | ORC 3734.02(Q) |

**Operations**

| Item | Y | N | DNI | NA | | Rule Reference |
|---|---|---|---|---|---|---|
| 28 | ☑ | ☐ | ☐ | ☐ | Are noise, dust, and/or odors being controlled? | 3745-27-19(B)(3) |
| 29 | ☑ | ☐ | ☐ | ☐ | Are adequate vector controls/control strategies available at the facility? | 3745-27-19(B)(4) |
| 30 | ☑ | ☐ | ☐ | ☐ | Are the access roads being maintained to minimize dust and erosion? | 3745-27-19(E)(2)(a) |
| 31 | ☐ | ☐ | ☑ | ☐ | Is a water truck being used or available to minimize dust generation on access roads? | 3745-27-19(E)(2)(a) |

| Facility Name: | Sunny Farms Landfill LLC | Date: | 12/7/2021 | Page 2 |
|---|---|---|---|---|

**Operations continued**

| Item | Y | N | DNI | NA | * indicates this item should be reviewed prior to the field inspection | Rule Reference |
|---|---|---|---|---|---|---|
| 32 | ☑ | ☐ | ☐ | ☐ | Is an operator, as defined in 3745-27-01, familiar with operations/documents? | 3745-27-19(E)(5) |
| 33* | ☑ | ☐ | ☐ | ☐ | Is the correct phase, listed on page 3, being filled? | 3745-27-19(E)(7)(b) |
| 34 | ☑ | ☐ | ☐ | ☐ | Is the working face supervised by a person knowledgeable of its operations? | 3745-27-19(E)(7)(c) |

**Litter**

| Item | Y | N | DNI | NA | | Rule Reference |
|---|---|---|---|---|---|---|
| 35 | ☑ | ☐ | ☐ | ☐ | Are measures in place to collect, contain and dispose of litter? | 3745-27-19(E)(9) |
| 36 | ☑ | ☐ | ☐ | ☐ | Are litter pickers, listed on page 3, on-site? | 3745-27-19(E)(9) |
| 37 | ☑ | ☐ | ☐ | ☐ | Is litter fencing in place? | 3745-27-19(E)(9) |

**Cover**

| Item | Y | N | DNI | NA | | Rule Reference |
|---|---|---|---|---|---|---|
| 38 | ☐ | ☐ | ☑ | ☐ | Is only soil being used as daily cover? | Court Order C |
| 39 | ☐ | ☐ | ☑ | ☐ | Is a minimum of six inches of soil daily cover applied and maintained? | 3745-27-19(F)(1) |
| 40 | ☐ | ☐ | ☐ | ☑ | Is one of the approved alternative daily cover (ADC) listed on page 3 being used? | 3745-27-19(F)(3) |
| 41 | ☐ | ☐ | ☐ | ☑ | Is the ADC being used in accordance with the Director's approval letter? | 3745-27-19(F)(3) |
| 42 | ☐ | ☐ | ☑ | ☐ | Is intermediate cover being protected from erosion (ie, silt fencing, vegetation)? | 3745-27-19(G)(4) |
| 43 | ☐ | ☐ | ☑ | ☐ | If transitional cover is in place, is it densely vegetated? (3745-27-08(D)(19)(b)) | 3745-27-19(H)(2)(a) |
| 44 | ☐ | ☐ | ☑ | ☐ | If final cap is in place, is it densely vegetated? (3745-27-08(D)(26)(e)(ii)) | 3745-27-19(H)(2)(b) |
| 45 | ☐ | ☐ | ☑ | ☐ | Is a 24-inch thick layer of well-compacted soil being used for intermediate cover? | Court Order 16D |
| 46 | ☐ | ☐ | ☑ | ☐ | Is a 36-inch thick layer of well-compacted soil being maintained on Area 2? | 3745-27-19(G)(4) |

**Surface Water Management**

| Item | Y | N | DNI | NA | | Rule Reference |
|---|---|---|---|---|---|---|
| 47 | ☑ | ☐ | ☐ | ☐ | Are stormwater features constructed/maintained for stormwater conveyance? | 3745-27-19(J)(1) |
| 48 | ☑ | ☐ | ☐ | ☐ | Are strategies in place to correct the conditions causing ponding or erosion? | 3745-27-19(J)(3) |

**Leachate Management**

| Item | Y | N | DNI | NA | | Rule Reference |
|---|---|---|---|---|---|---|
| 49 | ☑ | ☐ | ☐ | ☐ | Are leachate sump/tank readings, listed on page 3, within the compliance limits? | 3745-27-19(E)(1)(c) |
| 50 | ☐ | ☐ | ☑ | ☐ | Are leachate outbreaks documented on log of operations? | 3745-27-19(E)(11)(a) |
| 51 | ☐ | ☑ | ☐ | ☐ | Are leachate outbreaks present? | 3745-27-19(K)(1)(a)(c) |
| 52 | ☐ | ☐ | ☐ | ☑ | If leachate outbreaks are present, are the outbreaks being properly managed? | 3745-27-19(K)(1)(a)(c) |
| 53 | ☐ | ☐ | ☑ | ☐ | Is at least one back-up lift station pump available at the facility? | 3745-27-19(K)(2) |
| 54 | ☐ | ☐ | ☑ | ☐ | Is the hydrogen peroxide leachate treatment system operating? | 3745-27-19(K)(5) |
| 55 | ☑ | ☐ | ☐ | ☐ | Is leachate being treated/disposed on-site/off-site appropriately? | 3745-27-19(K)(5) |

**Ancillary Structures / Engineered Components**

| Item | Y | N | DNI | NA | | Rule Reference |
|---|---|---|---|---|---|---|
| 56 | ☑ | ☐ | ☐ | ☐ | Are observed engineered components functioning appropriately? | 3745-27-19(E)(1)(c) |
| 57 | ☑ | ☐ | ☐ | ☐ | Are observed ground water wells (3745-27-10) being maintained? | 3745-27-19(E)(1)(c) |
| 58 | ☑ | ☐ | ☐ | ☐ | Are observed explosive gas monitoring wells (3745-27-12) being maintained? | 3745-27-19(E)(1)(c) |
| 59 | ☑ | ☐ | ☐ | ☐ | Are observed gas extraction wells / gas vents being maintained? | 3745-27-19(E)(1)(c) |
| 60 | ☑ | ☐ | ☐ | ☐ | Is the hydrogen sulfide control system operating? | 3745-27-19(E)(1)(c) |
| 61 | ☑ | ☐ | ☐ | ☐ | Are the observed permanent Jerome meters/locations being maintained? | Court Order 16A |
| 62 | ☑ | ☐ | ☐ | ☐ | Is the primary flare operating? | 3745-27-19(E)(1)(c) |
| 63 | ☑ | ☐ | ☐ | ☐ | Is the back-up generator being maintained to ensure continous operation of the flares? | Court Order 16N |

**Railcars / Rail Unloading Building**

| Item | Y | N | DNI | NA | | Rule Reference |
|---|---|---|---|---|---|---|
| 64 | ☐ | ☐ | ☑ | ☐ | Is the rail unloading building's leachate tank high level alarm functioning? | 3745-27-19(E)(1)(c) |
| 65 | ☑ | ☐ | ☐ | ☐ | Is the rail unloading building's floor grates clear to allow the collection of leachate? | 3745-27-19(E)(1)(c) |
| 66 | ☑ | ☐ | ☐ | ☐ | Are measures in place to collect, contain and dispose of litter around the rail building? | 3745-27-19(E)(9) |
| 67 | ☑ | ☐ | ☐ | ☐ | Is litter fencing present between the rail unloading building and sedimentation pond? | Court Order 16S |

**Scales**

| Item | Y | N | DNI | NA | | Rule Reference |
|---|---|---|---|---|---|---|
| 68 | ☑ | ☐ | ☐ | ☐ | Is the front entrance scale operational? List certification on Page 4. | 3745-27-19(I) |
| 69 | ☑ | ☐ | ☐ | ☐ | Is the railcar scale operational? List certification on Page 4. | Court Order 16U |

| Facility Name: | Sunny Farms Landfill LLC | Date: | 12/7/2021 | Page 3 |
|---|---|---|---|---|

**Additional Documentation**

| Item | Y | N | | | |
|---|---|---|---|---|---|
| 70 | ☑ | ☐ | Was photo documentation gathered? | ☐ | Photos attached |
| 71 | ☑ | ☐ | Were hydrogen sulfide levels documented using a Jerome meter? | ☑ | Results attached |

| Item | | Information | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| 1 | | License terms/conditions: | ☐ | 2021 license conditions are being followed | | | | | | |
| 2 | | Permit-to-Install (PTI) terms and conditions applicable to the inspection: | Condition #25 | ☐ | AMDWR is 7500 tons/day | | | | | |
| | | | Condition #26 | ☐ | AMDWR report due by the 15th of following month | | | | | |
| | | | Condition #26 | ☐ | Leachate report due by the 15th of following month | | | | | |
| 3 | | Seneca County Court Consent Order | | Applicable orders from the July 26, 2019, Seneca County Court Consent Order (19-CV-0224) are incorporated into the checklist. | | | | | | |
| 4 | | List all alterations issued since the last inspection: | Alteration # | | Type: | | | | | |
| | | | Alteration # | | Type: | | | | | |
| | | | Alteration # | | Type: | | | | | |
| | | ☑ No alterations issued | Alteration # | | Type: | | | | | |
| | | | Alteration # | | Type: | | | | | |
| 16 | | Mark boxes to indicate what types of fire control equipment is available on-site: | | ☑ | Bulldozer | | ☑ | Soil Stockpile | | |
| | | | | ☑ | Compactor | | ☑ | 911 Service Available | | |
| | | | | ☑ | Fire Extinguisher(s) | | ☐ | Water Truck | | |
| 17 | | | Equipment available - mark boxes/quantity | ☑ | Bulldozers | #5 | ☑ | Compactor | #2 | |
| | | | Contingency plan available if no back-up | ☐ | Scrapers | # | ☑ | Trucks | #10 | |
| | | | Contingency plan reviewed | ☑ | Other | 3 excavators, 1 Locomotive, 1 Track mobile, 1 front end loader | | | | |
| 25 | | Disposal restrictions, 3745-27-19(E)(8), include NESHAP regulated asbestos unless authorized, liquids unless authorized, hazardous waste, PCBs, infectious waste, source separated yard waste, whole or shredded scrap tires, low-level radioactive waste, and semi-solid materials with free liquids | | | | | | | | |
| 33 | | Current permitted phase designation | | 12N | | | | | | |
| 36 | | Litter Pickers | Affiliation: | SFL/Temp agency | | | Number: | 2 (SWL) | | |
| 40 | | Alternative daily covers (ADC) approved for use and the approval date. Mark box(es) of the ADC being utilized. **In accordance with the consent order, only soil is currently approved for daily cover.** | | ☐ | Topcoat spray-on-slurry | 7/10/2001 | | | | |
| | | | | ☐ | VWPFR-12 Tarp | 7/10/2001 | | | | |
| | | | | ☐ | WP-1440SB Tarp | 7/10/2001 | | | | |
| | | | | ☐ | WP1440FR Tarp | 7/10/2001 | | | | |
| | | | | ☐ | WP2200SB Tarp | 7/10/2001 | | | | |
| | | | | ☐ | WP2600 Tarp | 7/10/2001 | | | | |
| | | | | ☐ | Integra 12FR Tarp | 7/10/2001 | | | | |
| | | | | ☐ | Proguard 11B Plus spray-on-slurry | 10/3/2006 | | | | |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| 49 | | Leachate sump readings - compliance level vs actual reading | Closed North PS #1, 2A | Compliance | 18 inches | Reading | 13 | Auto On | ☐ |
| | | | Closed North PS #2, 2C | Compliance | 18 inches | Reading | -- | Auto On | ☐ |
| | | | Closed North PS #3, 3A | Compliance | 18 inches | Reading | 12 | Auto On | ☐ |
| | | | Closed North PS #4, 3C | Compliance | 18 inches | Reading | 11 | Auto On | ☐ |
| | | | Closed North PS #5, 4A | Compliance | 18 inches | Reading | 15 | Auto On | ☐ |
| | | | Closed North PS #6, 4B (4C on SCATA) | Compliance | 18 inches | Reading | 10 | Auto On | ☐ |
| | | | Closed North PS #7, 5A | Compliance | 18 inches | Reading | 14/14.51 | Auto On | ☑ |
| | | | Closed North PS #8, 5B | Compliance | 18 inches | Reading | 0 | Auto On | ☐ |
| | | | Closed North PS #9, 6A | Compliance | 18 inches | Reading | 17/16.62 | Auto On | ☑ |
| | | | Closed North PS #10, 6B | Compliance | 18 inches | Reading | 14/13.82 | Auto On | ☑ |
| | | | Closed North PS #11, 7 | Compliance | 18 inches | Reading | 16/16.54 | Auto On | ☑ |

| Facility Name: | Sunny Farms Landfill LLC | | | | Date: | 12/7/2021 | | Page 4 |
|---|---|---|---|---|---|---|---|---|
| 49 | Leachate sump readings - compliance level vs actual reading | South Sump #8A | Compliance | 36 inches | Reading | 18/17.69 | Auto On | ☑ |
| | | South Sump #8B | Compliance | 36 inches | Reading | 17/17.21 | Auto On | ☑ |
| | | South Sump #9B | Compliance | 36 inches | Reading | 18/17.4 | Auto On | ☑ |
| | | South Sump #10A | Compliance | 36 inches | Reading | 16/16.37 | Auto On | ☑ |
| | | South Sump #12/13 | Compliance | 36 inches | Reading | | Auto On | ☐ |
| | | South Sump #13 | Compliance | 36 inches | Reading | 18.33 | Auto On | ☑ |
| 49 | Leachate storage tanks inspection. Tank readings, capacity and high level shutoff are recorded in feet | Tank #1 (East) | Secondary Containment | ☐ | | Visual Insp (leaks, rust) | | ☐ |
| | | Tank Reading | 0 | Height | 16.12 | High Level Shutoff | | 13 |
| | | Tank #2 (West) | Secondary Containment | ☑ | | Visual Insp (leaks, rust) | | ☑ |
| | | Tank Reading | 3.61 | Height | 24.18 | High Level Shutoff | | 20 |
| | | Tank #3 (South) | Secondary Containment | ☑ | | Visual Insp (leaks, rust) | | ☑ |
| | | Tank Reading | 14.9 | Height | 28.06 | High Level Shutoff | | 26.5 |
| 60 | Hydrogen sulfide control system | # of control boxes on-site | | 10 | | # of control boxes in use | | 4 |
| 62 | Flare operations | Flare 1 | Temperature: | | Flow: | | Pressure: | |
| | | Flare 3 | Temperature: | 1402 | Flow: | 3325 | Pressure: | 205 |
| 68 | Front entrance scale | Last Inspection: | 7/17/2021 | Agency: | Brechbuhler Scales | | | |
| 69 | Rail scale | Last Inspection: | 8/15/2021 | Agency: | Seneca Weights and Measure and Rail Scale | | | |

| # | Item/Information Section |
|---|---|
| | |

| # | General Comments Section |
|---|---|
| | |

| Facility Name: | Sunny Farms Landfill LLC | Date: | 12/7/2021 | Page 5 |
|---|---|---|---|---|

**Select Waste**

| Item | Y | N | DNI | NA | | Rule Reference |
|---|---|---|---|---|---|---|
| 72 | ☑ | ☐ | ☐ | ☐ | Is the select waste layer (SWL) being placed? If Yes, complete items #73-82 | 3745-27-19(D) |
| 73 | ☑ | ☐ | ☐ | ☐ | Is the SWL being spread and not compacted? | 3745-27-19(D)(1)(a) |
| 74 | ☑ | ☐ | ☐ | ☐ | Does the SWL contain items under two feet in length? | 3745-27-19(D)(1)(b) |
| 75 | ☑ | ☐ | ☐ | ☐ | Does the SWL allow the flow of liquids to the leachate collection system? | 3745-27-19(D)(1)(c) |
| 76 | ☑ | ☐ | ☐ | ☐ | Is the SWL free of fines and small particles? | 3745-27-19(D)(1)(d) |
| 77 | ☑ | ☐ | ☐ | ☐ | Is the SWL being placed as a single lift of a minimum of five feet? | 3745-27-19(D)(1)(e) |
| 78 | ☑ | ☐ | ☐ | ☐ | Was the SWL documentation submitted to the operating record? | 3745-27-19(D)(2) |
| 79 | ☑ | ☐ | ☐ | ☐ | Was the date of the SWL documented? | 3745-27-19(D)(2)(a) |
| 80 | ☑ | ☐ | ☐ | ☐ | Was the location of the cell/phase of the SWL documented? | 3745-27-19(D)(2)(b) |
| 81 | ☑ | ☐ | ☐ | ☐ | Was the thickness of the SWL documented? | 3745-27-19(D)(2)(c) |
| 82 | ☑ | ☐ | ☐ | ☐ | Was the source and composition of the SWL documented? | 3745-27-19(D)(2)(d) |

| Austin Nainiger | Austin Nainiger | 12/7/2021 |
|---|---|---|
| **Print Name of Inspector Completing Inspection Form** | **Signature** | **Date** |

**Last Revised: January 29, 2021**

| Date | Time | Reading PPB | Lat | Long. | Location | Temp. | Speed | Wind Direction | Press. | Operator | Notes |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 12/7/2021 | | | | | | 25 | 6 | W | 30.3 | AN | |
| | 11:15 AM | 0 | 41.137635° | -83.418575° | Foundation Park South entance | | | | | | none |
| | 11:15 AM | 0 | 41.137635° | -83.418575° | Foundation Park South entance | | | | | | none |
| | 11:33 AM | 0 | 41.10803° | -83.410849° | SFL entrance | | | | | | none |
| | 11:38 AM | 0 | 41.094104° | -83.400496° | TR108 Stationary meter | | | | | | none |
| | 11:42 AM | 0 | 41.099981° | -83.396511° | 1587 CR 37 | | | | | | none |
| | 11:45 AM | 0 | 41.098148° | -83.401439° | Sheller Cemetary US 23 | | | | | | none |
| | 11:52 AM | 0 | 41.083946° | -83.401125° | 2679 US 23 | | | | | | none |
| | 11:55 AM | 0 | 41.088616° | -83.401396° | 2394 US 23 | | | | | | none |
| | 12:00 PM | 0 | 41.093875° | -83.406635° | TR108 at RR | | | | | | none |